


## RELAY WIRING DIAGRAM



1. Compressor positive wire (Red)
2. To fused battery/power source (+)  
(See amp draw of compressor for rating)
3. To one pole of pressure switch
4. Ground (-)